Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1539	(33/706,708,366.11,366.21,366.25, 366.26,366.27,1pt).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/19 12:57
S2	31	electrical and contacts and measurement and angular and ((33/706,708,366.11,366.21,366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:15
S3	5	electrical and contacts and measurement and angular and arcuate and ((33/706,708,366.11, 366.21,366.25,366.26,366.27,1pt). CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:17
S4	723	electrical and contacts and measurement and angular and arcuate voltage and cpu and ((33/706,708,366.11,366.21,366. 25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:17
S5	0	electrical with contacts with measurement with angular with arcuate with voltage with cpu and ((33/706,708,366.11,366.21,366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:18
S6	0	electrical and contacts and measurement and angular and arcuate and voltage and cpu and ((33/706,708,366.11,366.21,366. 25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:18
S7	0	electrical and contacts and measurement and angular and voltage and cpu and ((33/706,708, 366.11,366.21,366.25,366.26,366. 27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:18
S8	21	electrical and contacts and measurement and angular and voltage and ((33/706,708,366.11, 366.21,366.25,366.26,366.27,1pt). CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:18
S9	3	electrical and contacts and measurement and angular and arcuate and voltage and ((33/706, 708,366.11,366.21,366.25,366.26, 366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:19

10/15/07 2:35:31 PM Page 1
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

			•			•
S10	0	electrical and contacts and measurement and angular and arcuate and voltage and cpu and ((33/706,708,366.11,366.21,366. 25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR ·	OFF	2004/09/03 09:19
S11	0	electrical and contacts and measurement and angular and arcuate and voltage and computer and ((33/706,708,366.11,366.21, 366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:20
S12	1	electrical and contacts and measurement and angular and arcuate and voltage and data and ((33/706,708,366.11,366.21,366. 25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:20
S13	0	(electrical adj contacts) and cpu and rom and ((33/706,708,366.11, 366.21,366.25,366.26,366.27,1pt). CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:56
S14	0	(electrical adj contacts) and rom and ((33/706,708,366.11,366.21, 366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:57
S15	0	(electrical and contacts) and rom and ((33/706,708,366.11,366.21, 366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:57
S16	32	rom and ((33/706,708,366.11,366. 21,366.25,366.26,366.27,1pt).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:57
S17	7	rom and computer and ((33/706, 708,366.11,366.21,366.25,366.26, 366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:57
S18	0	rom and computer and contacts and ((33/706,708,366.11,366.21, 366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:57
S19	7	rom and computer and electrical and ((33/706,708,366.11,366.21, 366.25,366.26,366.27,1pt).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/09/03 09:57

10/15/07 2:35:31 PM Page 2 C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S22	15	preset adj memory adj location	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:04
S23	0	electrical adj contacts and preset adj position adj measurement adj data	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:05
S24	0	preset adj position adj measurement adj data	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:05
S25	3	preset adj position adj measurement	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:05
S26	1696	(33/706,708,366.11,366.21,366.25, 366.26,366.27,1pt).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:14
S27	402	electrical adj contacts and "33"/\$. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:15
S28	31	electrical adj contacts and memory and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/08 13:15
S29	928	(33/708,366.24,366.25,366.26,1pt). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:04

10/15/07 2:35:31 PM Page 3
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

			I	I		
S30	928	(33/708,366.24,366.25,366.26,1pt). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/05/18 14:16
S31	5	electrical adj contact and memory and S30	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:11
S32	32	contact and memory and S30	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:12
S33	7	electrical adj inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:17
S34	2	("4494620").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:14
S35	9	("3566983" "4258811" "4341275" "4401173").PN. OR ("4494620").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/02/10 17:15
S36	27331	electrical and bubble	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:17
S37	513	electrical and bubble and level and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:17
S38	296	electrical and bubble and level and contact and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:32

S39	8	electrical and bubble and contact and data and S30	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/02/10 17:32
S42	936	(33/708,366.24,366.25,366.26,1pt). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:06
S43	167	(33/366.24).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:07
S44	2	("3791042").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:07
S47	130	pendulum and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:25
S48	101	pendulum and S43	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:22
S49	8	pendulum and arcuate and S43	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:24
S50	0	pendulum and arcuate and memory and computer and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:24

10/15/07 2:35:31 PM Page 5
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S51	0	pendulum and arcuate and memory and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:24
S52	12	pendulum and arcuate and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:26
S54	3	pendulum and arcuate and voltage and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:26
S55	0	pendulum and arcuate and voltage and contacts and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:26
S56	19	pendulum and arcuate and voltage and contacts and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 14:31
S57	16	pendulum and arcuate and voltage and contacts and memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:02
S64	894	arm and arcuate and voltage and contacts and memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:02
S65	4	arm and arcuate and voltage and contacts and memory and inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:03

10/15/07 2:35:31 PM Page 6
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S66	4	arm and arcuate and contacts and memory and inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:03
S67	24	arm and arcuate and contacts and inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:18
S69	26	pendulum and arcuate and contacts and inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:23
S71	32	pendulum and arcuate and electrical and inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:26
S72	94	pendulum and arcuate and electrical and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:26
S73	51	pendulum and arcuate and electrical and contacts and "33"/\$. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 15:26
S74	36	pendulum and arm and arcuate and electrical and contacts and "33"/\$. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2005/05/12 16:14
S75	49	(cpu or computer) and display and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 16:14

10/15/07 2:35:31 PM Page 7
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

	1	1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		Ι	 -1	1
S76	4	(cpu or computer) and rom and display and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 16:17
S78	0	(cpu or computer) and ROM and inclinometer and S42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 16:17
S79	223	(cpu or computer) and ROM and inclinometer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 16:17
S80	187	(cpu or computer) and ROM and inclinometer and display	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 16:18
S81	13	(cpu or computer) and ROM and inclinometer and display and S74/\$. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/05/12 16:18
S82	1	borehole and cpu and (angular adj displacement)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 13:49
S83	15	borehole and cpu and angular and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 13:49
S84	1	borehole and cpu and ROM and angular and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON Å.	2006/05/18 13:50

10/15/07 2:35:31 PM Page 8 C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S85	92	borehole and cpu and ROM and angular	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 13:51
S86	81	borehole and cpu and ROM and angular and (electrical adj contact)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 13:58
S87	82	borehole and cpu and ROM and angular and (electrical with (element or contact))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 14:00
S88	89	borehole and cpu and ROM and (electrical with (element or contact))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 14:03
S89	129	borehole and computer and "33"/\$. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 14:03
S90	12	borehole and computer and cpu and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 14:07
S91	9	borehole and computer and cpu and angle and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/18 14:07
S92	983	(33/708,366.24,366.25,366.26,1pt). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/05/18 14:16
S93	6	(("2637527") or ("3004613") or ("3077233") or ("3004613")).PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/07/18 10:27

				,		r
S94	1788	(33/706,708,366.11,366.21,366.25, 366.26,366.27,1pt).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	OFF	2007/03/16 15:39
S95	2137	(702/80,97,158,160,187,150).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/02/09 13:20
S96	1214	memory and S95	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/09 13:20
S98	97	(look adj up) with table and S95	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/09 13:21
S99	76	(look adj up) with table and memory and S95	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/09 13:21
S10 0	13	(look adj up) with table and memory and preset and S95	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/09 13:33
S10 1	16	(look adj up) with table and memory and preset and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/09 13:34
S10 2	2160	PRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:18

10/15/07 2:35:31 PM Page 10
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S10 3	. 330	PRAM and computer	US-PGPUB; USPAT;	OR	OFF	2007/03/14 13:19
,			USOCR; EPO; JPO; DERWENT; IBM_TDB			
S10 4	0	PRAM and computer and "33"/\$. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:19
S10 5	236	PRAM and computer and table	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:19
S10 6	202	PRAM and computer and table and memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:19
S10 7	73	PRAM and computer and table and memory and measure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF.	2007/03/14 14:09
S10 8	27	PRAM with memory and computer and table and measure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:23
S10 9	0	PRAM with memory and computer and table and measure and (insulated adj contacts)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:22
S11 0		PRAM with memory and computer and table and measure and contacts	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 13:22

10/15/07 2:35:31 PM Page 11
C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S11 1	2257	distance same (look adj up adj table)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2007/03/14 14:09
S11 2	16	distance same (look adj up adj table) and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 14:12
S11 3	20	distance with measure and (look adj up adj table) and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 14:13
S11 4	0	distance with measure near (look adj up adj table) and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 14:13
S11 5		distance with measure with (look adj up adj table) and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 14:13
S11 6	20	distance with measure and (look adj up adj table) and "33"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF ·	2007/03/14 14:16
S11 7	24	distance with measure with (look adj up adj table)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/14 14:14
S11 8	28	("0454516" "0677574" "0979248" "1156694" "1196789" "1269336" "1659939" "2362907" "2855687" "3333343" "4468860" "4845646").PN. OR ("5154003").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/03/14 14:25

10/15/07 2:35:31 PM Page 12 C:\Documents and Settings\TCourson\My Documents\EAST\Workspaces\10_660_543_Measuring Angle & Linear Displacement.wsp

S11 9	1819	(33/706,708,366.11,366.21,366.25, 366.26,366.27,1pt).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/15 14:22
S12 0	1572	(33/366.24,783,784,806,810,707). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/15 14:22
S12 2	2153	(702/80,97,150,158,160,187).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/15 14:22
S12 3	1861	(33/706,708,366.11,366.21,366.25, 366.26,366.27,1pt).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/15 14:22
S12 4	1589	(33/366.24,783,784,806,810,707). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/15 14:22
S12 5	2328	(702/80,97,150,158,160,187).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/15 14:22